

Regarding:



Photo - Window in study - office

Limitations:



Photo - Rear wall water entry locations

Purpose and Scope:



Photo - Moisture reading below dining room window


Information Provided:



Photo - Study carpet tack strip

Findings or Observations:

Exterior



Drawing - Window movement

Conclusions:



Photo - Rear wall plastic sheeting

Findings or Observations:

Interior



Photo - Hole in sheathing below dining room window.

Recommendations:



Photo - Dining room corner, caulk and flashing